


Nov. 15, 2003, VOLUME IV NUMBER XXII


SERVING THE REGION'S INDO-AMERICAN COMMUNITY

Fire destroys family's home



Firefighters work to put out the blaze that destroyed this home in Shrewsbury, Mass., while its owners were out visiting relatives on Diwali. The family had only been living in the home for a month after moving from Pittsburgh.





Gusset plates are the weak links in lightweight trusses, only penetrating the wood by a quarter-inch and often pulling loose prior to installation.






WARNING

Many firefighters have lost their lives when a trussed roof has failed. A good rule to follow is that when a significant amount of fire exists in the truss area of a roof structure, firefighters should not be on or under a truss roof.

PEAK STILL INTA CT




PEAK COLLAPSED



Flat 2 imes 4 trusses covered with plywood can easily be severed by power saws.



VOID SPACE



Flat 2 imes 4 trusses create a cockloft (more accurately, a trussloft) on each floor.

